

GRE Draft Policy on Lab Coats

- (1) Labcoats (and other protective equipment) should always be worn when handling hazardous materials, performing hazardous techniques using these materials or when in an environment when exposure to such materials is a significant possibility.
- (2) Wherever feasible, handling of hazardous materials should be restricted to the specific areas designated.
- (3) Labcoats should not be worn in communal areas and areas where food and drink is likely to be consumed.
- (4) Lab coats should be washed on a regular basis.