

## *Stray Field Guidelines*

<b>5 Gauss Maximum</b>	<b>10 Gauss Maximum</b>	<b>50 gauss Maximum</b>	<b>500 Gauss Maximum</b>
Cardiac Pacemakers	Computers	Magnet Power Supply	Magnetic Wrenches
CRT Displays	Magnetic Storage Media	Liquid Helium Monitor	Magnetic Screwdrivers
Oscilloscopes	Credit Cards	Liquid Nitrogen Monitor	Magnetic Hardware
Motor Vehicles	Watches	Other Instrumentation	All Other Magnetic Items